

BODY INTERIOR

5110-01

GENERAL INFORMATION



1. MAJOR CHANGES

► Instrument Panel

Instrument panel	
Old	
New	
<ul style="list-style-type: none"> - The design and material of IP have been changed. - An invisible type passenger air bag module has been applied. 	

LH side fascia panel & molding	
Old	New
	
<p>The design of LH side fascia panel & molding has been changed.</p>	




Cluster fascia panel	
Old	New
	 <p>Cluster fascia molding</p> <p>RH cluster fascia panel</p>
<p>RH cluster fascia panel and molding have been newly applied.</p>	

Modification basis	
Application basis	
Affected VIN	

Center fascia panel & molding, RH side fascia panel & molding

<p>Old</p>	<p>New</p>
-------------------	-------------------

- The design of center fascia panel & molding has been changed.
- The design of RH side fascia panel & molding has been changed.
- RH center fascia panel has been newly applied.



Crash pad upper cover

<p>Old</p>	<p>New</p>
-------------------	-------------------

The name of crash pad upper tray has been changed to "crash pad upper cover" and its design also has been changed.

Center fascia lower panel

<p>Old</p>	<p>New</p>
-------------------	-------------------

The design of center fascia lower panel has been changed (lower tray, heater and A/C control assembly).

RH glove box housing extension

Newly introduced

RH glove box housing extension panel has been newly added on the right side of glove box housing.

Modification basis	
Application basis	
Affected VIN	

► Front Console



► Door Trim



Modification basis	
Application basis	
Affected VIN	

2. MAJOR CHANGES (as of Feb. 2014)

Floor front mat

Increased height of floor front mat on unit installation area due to changed position of E-coupling control unit

- AIR CONDITIO
- AIR BAG
- SEAT
- SUNROO F
- BODY INTERIOR
- BODY EXTERIO
- BODY REPAIR

Modification basis	
Application basis	
Affected VIN	